


# APPENDIX F

## BANCS MAPS



**Legend**

Outfalls for Evaluation

**BEHI Rating**


- Extreme
- Very High
- High

- Sanitary Manhole
- Sanitary Structure
- Sanitary Line
- Drainage Manhole
- Drainage Structure
- Drainage Line

Ratings		
	BEHI	NBS
#1	Very High	Very High




# 000166 Holmes Run BANCS Assessment




Environment & Infrastructure  
14424 Abenmarie Point Place, Suite #115  
Chantilly, VA 20151






# **Strawberry Run** **BANCS Assessment**




Environment & Infrastructure  
 14424 Abernethy Point Place, Suite #115  
 Chantilly, VA 20151






# Taylor Run BANCS Assessment



Environment & Infrastructure  
14424 Abernethy Point Place, Suite #115  
Chantilly, VA 20151






# **Timber Branch** *BANCS Assessment*




**wood.**

Environment & Infrastructure  
 14424 Abenmarie Point Place, Suite #115  
 Chantilly, VA 20151






# Unnamed Trib Walleston BANCS Assessment




Environment & Infrastructure  
14424 Abenmarie Point Place, Suite #115  
Chantilly, VA 20151





# Holmes Run BANCS Assessment



**wood.**

Environment & Infrastructure  
14424 Abenmarie Point Place, Suite #115  
Chantilly, VA 20151